

OM371 DEW POINT TRANSMITTER

Compact Dew Point Temperature Transmitter / Switch

Application:

The exact monitoring of dew point temperature in compressed air systems, dryers for plastic and other indus¬trial processes is becoming increasingly more important. OM371 series with a measuring range -60...60°C Td (-112...140°F Td) is the ideal solution for such applications. The core of the transmitter is the monolithic measurement cell type HMC01, developed by Omicron Sensing in thin film technology. An autocalibration procedure which is integrated in the device and years of experience in low humidity adjustment make an accuracy of <2°C Td (±3.6°F Td) possible.





Autocalibration:

Dew point temperatures in the range of -60...-20°C (-76...-4°F) at room temperature correspond to relative humidity values of 0.08...5.37% RH. The measurement of these low humidity values is not possible with conventional capacitive measurement methods. For the 0M371 series a special autocalibration procedure is utilized to achieve high accuracy measurements at lowest dew points too.

Output:

Model T: The transmitter has two freely selectable and scaleable outputs for dew point, frost point or

ppm volume concentration.

 $\label{eq:solution} \mbox{Model S} \ : \ \ \mbox{The switch with two relay outputs is designed for control and alarm purposes.} \ The status for \ \mbox{The switch with two relay outputs} \ \ \mbox{The switch with two relay} \ \ \mbox{The status} \ \mbox{The statu$

early warning and main alarm is indicated by LED's. Adjustment of the Td/Tf set point and

hysteresis can be achieved with the optional configuration software.

ConfigurationSoftware:

The optional configuration software allows flexible and easy adjustment of the analogue resp. relay outputs to the respective requirements.


The adjustment / calibration of the transmitters can easily be performed.

Screw Connection for Mounting -360° positionable:

The construction of this screw connection enables any position / rotation of the mounted transmitter.

So an optimal position of the display resp.

the cable outlet is guaranteed.



Typical Application:

Monitoring of compressed air systems : measuring range -60...60°C Td (-76...140°F Td) Refrigerant type dryer : accuracy of measurement ± 2 °C Td (± 3.6 °F Td)

Absorption dryer : two Td/Tf alarm outputs

Plastics dryer : autocalibration

pressure tight up to 100 bar (1450psi)

OM371 DEW POINT TRANSMITTER

Compact Dew Point Temperature Transmitter / Switch

Technical Data:

Measuring Quantities


Dew Point (Td)

Dew Point Sensor HMC01

Measuring Range : 25°C to + 65°C

Accuracy : Traceable to intern. standards, administrated

by NIST, PTB, BEV...



Response Time t_{90} : 80 sec.

-20°C Td —> -40°C Td

 $(-4^{\circ}F \text{ Td} \longrightarrow -40^{\circ}F \text{ Td})$

10 sec

-40°C Td —> -20°C Td

 $(-40^{\circ} \text{F Td} - - > -4^{\circ} \text{F Td})$

Volume concentration

Measuring range :

20...200 000ppm

Accuracy at 20°C (68°F) and 1013mbar : 5ppm + 20% of reading

Outputs

Selectable and scalable : 0 - 10V -1mA < I, < 1mA analogue output for Td, Tf, Wv : 4 - 20mA R < 500 Ohm

General

Supply Voltage : 21...28V DC

Current Consumption at 24V DC : voltage output: typ. 40mA / during autocalibration: 100mA

current output: typ. 80mA / during autocalibration: 100mA

Pressure Range : 0...20bar (0...290psi)

Sensor protection : stainless steel sintered filter


Working temperature range : probe: -40...70°C (-40...158°F)

electronic. -40...60°C (-40 140°F)


Storage temperature range : -40...60°C (-40...140°F)

Electromagnetic compatibility : EN 61326-1 EN61326-2-3 ICES-003 ClassB according to Industrial Environment FCC Part15 ClassB

Dimensions (mm)



spanner width: 27 or 24





OM371 DEW_POINT_TRANSMITTER

Compact Dew Point Temperature Transmitter / Switch

Basic Sampling Cell:

The basic sampling cell offers the possibility to integrate the 0M371 into an existing or self-constructed sampling system

1 = G 1/2" ISO

2 = G 1/4"

3 = G 1/4"

Sampling Cell with Quick Connector upto 10 bar (145psi):

The sampling cell is specially developed for use in compressed air lines and has a quick-connector suitable for standard compressed air connections. It allows for the cell to be fitted and removed without interrupting the process. The flow of gas can be adjusted Susing a bleed screw.



2 = Bleed screw

3 = Quick connector



HOW TO ORDER

A.	Har	WD	are	Coni	ıg	urai	lon
----	-----	----	-----	------	----	------	-----

Model transmitter

switch

Pressure range up to 20bar (290psi)

Pressure tight G1/2" male thread

feedthrough 1/2" NPT thread

Display : without display

with display D08

🗘 Software Configuration :

Physical parameters :

of the output

dew point temperature Td frost point temperature Tf

volume concentration

(°C/° F)

(ppm)

output/relay 1

output/relay 2

select according to Ordering Guide (C,D,P)

OM371

T

S

E

HAO3

HAO7

Type of output signal : 0-1V

0-5V

0-10y 0-20mA

4-20mA

5 6

1

2

3



OM371 DEW POINT TRANSMITTER

Compact Dew Point Temperature Transmitter / Switch

Software Configuration:

Measured value units : metric / SI

for T /Td /Tf non metric / US

Scaling of Td/Tf-output: -40...60 (Td/Tf02) -60...20 (Td/Tf65) Other Td/Tf-scaling Select according to order guide (Tdxx or Tfxx)

(in °C or °F) 10...50 (Td/Tf03) refer to data sheet

" T-Scalings"

 $ppm\ range\ Wv \qquad \qquad : \qquad \qquad 0...100ppm \qquad (X01)$

0...500ppm (X02) select according to Ordering Guide

0...1000ppm (X03) other measuring range:

Setting of alarm output : standard for configuration CC R1: -40°C (-40°F) R2: -30°C (-31°F)

H1: -2°C (35.6°F) H2: 2°C (35.6°F)

other set points: relay 1:_____ relay 2:____

hysteresis 1:_____ hysteresis 2:_____

Accessories:

Sampling cell with quick connector : (HA050102) basic sampling cell : (HA050103) configuration software + interface cable : (HA010604) stainless steel sintered filter : (HA010103) display : (D08)

Ordering Example:

OM371-TEHAO7D08/CD2-Td03

E01

SP